





1. Fastening screw for base

U naulakko




1. ↑ X2

Verso




1. ↑ X3

Porter



1. ↑ X3

Renki



1. ↑

Attention!  
The fastening screws must be tightened by hand,  
not by machine.